

Cert. No.: MV25418191325
Facility: Datarecovery.com
Address: 110 North Research Dr

Address: 110 North Research Dr. Edwardsville, IL 62025

Svc. Order: HL-DAT025001H-1

Building: 110 Room: Data Lab

Contact: Michael Katich

Make: ENVIRCO

Model: <None>
Unit Type: Clean Bench

SN: S09-120V-00790

Airborne Nonviable Particle Count Test Report

Clean Zone: S09-120V-00790 Status: Operational/Dynamic Cust ID: NA Duration: 1.0 Min(s).

Report Date: 04/18/2025 Class: ISO-4 Area: 7.18 ft² Flow Rate: 28.3 LPM

Retest Date: 04/30/2026 Occupants: 1 Total Sample Vol.: 28.3 L

Testing is performed to satisfy ISO 14644-1:2015

Pass

PPCM (um) ≥ 0.3

 Loc
 Count 1
 Count 2
 Count 3
 Average Result
 T. C°
 % rH

 1)
 0
 NA
 NA
 0
 Pass
 26.6
 44

Class Limit: 1,020 26.6 44

Sample Volume Test: Pass
Class Limit Location Test: Pass



Print Date: 04/18/2025

This record was electronically signed by:

Michael Vandeveer 4/18/2025 7:16:53 PM

Field Service Technician

I certify that this record is a true and accurate representation of work performed.



Cert. No.: MV25418191325
Facility: Datarecovery.com
Address: 110 North Research Dr.

Edwardsville, IL 62025

Svc. Order: HL-DAT025001H-1

Building: 110 Room: Data Lab Contact: Michael Katich Make: ENVIRCO
Model: <None>

Unit Type: Clean Bench

SN: S09-120V-00790


Airborne Nonviable Particle Count Test Report

Clean Zone: S09-120V-00790 Status: Operational/Dynamic Cust ID: NA Duration: 1.0 Min(s).

Report Date: 04/18/2025 Class: ISO-4 Area: 7.18 ft² Flow Rate: 28.3 LPM

Retest Date: 04/30/2026 Occupants: 1 Total Sample Vol.: 28.3 L

Airborne Nonviable Particle Count Diagram:





eData v7.0.5.2

Print Version: Service Manager v7.0.5.2

Print Date: 04/18/2025



representation of work performed.





Cert. No.: MV25418191325
Facility: Datarecovery.com
Address: 110 North Research Dr.

Edwardsville, IL 62025

Svc. Order: HL-DAT025001H-1

Contact: Michael Katich

Building: 110 Room: Data Lab Make: ENVIRCO
Model: <None>
Unit Type: Clean Bench

SN: S09-120V-00790

The following NIST-Traceable equipment were used to perform this test:

Equipment ID	Manufacturer	Model	Serial #	Calibration Due
012665	Govee	H5075	EQ12665	09/27/2025
006619	Lighthouse	Apex P3	1501105008	09/09/2025

Page: 3/3 web: www.techsafety.com

eData v7.0.5.2

Print Version: Service Manager v7.0.5.2

Print Date: 04/18/2025



This record was electronically signed by:

Michael Vandeveer 4/18/2025 7:16:53 PM

Field Service Technician

I certify that this record is a true and accurate representation of work performed.